


QUOTATION

Name of work :- Repairing and Overhauling of ceiling fans, Exhaust fans at 41 lab, HC opd, GHT lift, Hall-12 fblock lift, OCL-202D, H.No. 476, 467, 471, gate build. 205, DOAA canteen, Telephone exchange etc. as per enclosed complaints at IIT Kanpur.

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
1	Rewinding of following fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnormal height and refixing as required. (Old burnt wire shall be reatin by the contractor.)				
a)	new model 48"	1.00	Nos.		
b)	old model 48" / new model 56"	4.00	Nos.		
2	Rewinding of exhaust fans of following sizes i/c dismantling cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnorml height and refixing as required.(old burnt wire shall be retain by the contactor.)				
a)	Exhaust fan 12"	4.00	Nos.		
2	Overhauling of ceiling fan of any size including dismantling and refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/ split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.	48.00	Nos.		
3	Overhauling of exhaust fan of any size including dismantling of all parts and cleaning the fan with kerosene oil / petrol removing ball bearing/ bush and refixing after greasing/ oiling including testing and commissioning as required complete. (spares will be supplied by the Dept.)	6.00	Nos.		

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
4	Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan.	25.00	Nos.		
5	Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc.	9.00	Nos.		
6	Dismantling & disconnecting and refixing of exhaust fan from 12" to 24 " size with required nut bolts, fasteners, rag bolts etc. as required.	6.00	Nos.		
7	Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.	28.00	Nos.		
8	Supply of following size ball bearings.				
a)	Ball bearing 6201 (NBC - make)	14.00	Nos.		
b)	Ball bearing 6202 (NBC - make)	16.00	Nos.		

Total Rs.


 अधिशासी अभियंता (वि०) E.E. (Elect.
 संवि० वि०, भागप्रौढ संस्थान, कानपुर
 I.W.D., I.I.T., Kanpur
